



$c=0\sim 1200\text{ mm}^2$

$c=1200\sim 2500\text{ mm}^2$

$c=2500\sim 3500\text{ mm}^2$

$c=3500\sim 4500\text{ mm}^2$

$c=4500\sim 5500\text{ mm}^2$

$c=5500\sim 6500\text{ mm}^2$

if $a \cdot b = c$ then $h = 200\text{ mm}$

if $a \cdot b = c$ then $h = 250\text{ mm}$

if $a \cdot b = c$ then $h = 300\text{ mm}$

if $a \cdot b = c$ then $h = 350\text{ mm}$

if $a \cdot b = c$ then $h = 450\text{ mm}$

if $a \cdot b = c$ then $h = 500\text{ mm}$